


J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

REPLACEMENT SHEET

1/12

FIG. 1





J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

REPLACEMENT SHEET

2/12

FIG. 2A




FIG. 2B




FIG. 2C





FIG. 2D



FIG. 2E






J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

REPLACEMENT SHEET

3/12

FIG. 3

310








FIG. 4






J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

5/12



FIG. 5







FIG. 6






J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

7/12

FIG. 7





J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

8/12

FIG. 8




FIG. 9A




FIG. 9B




FIG. 9C






FIG. 9D





9/12

FIG. 10






J. MERRIAM 1
SERIAL NO.: 09/695,647
PETER H. PRIEST (919-806-1600)

10/12

FIG. 11






11/12

FIG. 12

110





12/12

